Black Dog Gunsmithing LLC Q4 2025 Price List

Pricing is either fixed or variable based on project complexity or condition. See the legend at the end for some examples. If you have questions or wish to request an estimate, please contact me.

| Service | Low Variable | High Variable | Fixed Cost |
|--|--------------|---------------|------------|
| Hourly rate for work tasks not listed below. | | | \$80 |
| Rush work surcharge added to invoice - Jump the queue and waitlist. Rush projects are done first before anything else and the only time they are not worked on is when there's something out of my control preventing them (parts/feedback/range openings/etc.) Charge is per gun. | | | \$100 |
| Operator-level disassemble, clean, inspect, oil, reassemble. Do not include safety & function check, headspace check, or test fire. Rust removal limited to corrosion which would likely affect function. | \$150 | \$250 | |
| Full disassemble, clean, parts inspection, oil, reassemble, headspace check, safety & function check, test fire (ammo cost not included). Includes <u>surface</u> rust removal. | \$250 | \$400 | |
| Test fire (does not include ammo, safety/function & headspace check must have been performed previously) | | | \$50 |
| Boresight customer gun | | | \$30 |
| Sight-in customer gun 25-100 yards (ammo not included). Requires necessary cleaning, prior safety & function check, headspace check. | | | \$50 |
| Drill & tap receiver for sights (+\$20 for each hole) | | | \$40 |
| Install front/mid-rib shotgun bead (bead not included) +\$20 per bead | | | \$40 |
| Check headspace - Requires partial to full disassembled cleaning. Does not include headspace gauge rental if needed. | | | \$40 |
| Engraving Contact Saft Custom or Northern Knives | | | |
| Chamber casting and identification | | | \$75 |
| Remove stuck fired case from chamber | | | \$80 |

Black Dog Gunsmithing LLC Q4 2025 Price List

Pricing is either fixed or variable based on project complexity or condition. See the legend at the end for some examples. If you have questions or wish to request an estimate, please contact me.

| Service | Low Variable | High Variable | Fixed Cost |
|--|--------------|---------------|------------|
| Remove stuck live round chamber - NOT ACCEPTED | LOW Variable | High Variable | rixeu Cost |
| | | | *** |
| Remove bore obstruction | | | \$80 |
| Cut, crown, thread standard pitch | | | \$260 |
| Metric threading surcharge | | | \$40 |
| Cut and crown barrel | | | \$80 |
| Recrown muzzle by hand (11deg) | | | \$80 |
| Tapered (Sig or similar) shoulder muzzle threading surcharge | | | \$60 |
| Recrown muzzle after threading if needed. | | | \$40 |
| Install prefit barrel, check headspace, test fire. Disassembly, and necessary cleaning billed at hourly rate in addition. | | | \$300 |
| Fit barrel blank to action, chamber, check headspace, test fire (does not include barrel, headspace gauge or reamer rental if needed). Flat breech. Other breech surcharges below. | | | \$400 |
| Ressed breach surcharge | | | \$75 |
| Cone breech surcharge | | | \$50 |
| Extractor cut surcharge | | | \$100 |
| Time replacement barrel for sights. | | | \$40 |
| Break in new barrel (does not include ammo) | | | \$150 |
| Bolt lug lapping | \$40 | \$80 | |
| Safety/function check (does not include necessary cleaning) | | | \$50 |
| Aftermarket trigger installation, safety check. | \$75 | \$150 | |
| Borescope inspection | | | \$40 |

Black Dog Gunsmithing LLC Q4 2025 Price List

Pricing is either fixed or variable based on project complexity or condition. See the legend at the end for some examples. If you have questions or wish to request an estimate, please contact me.

| Service | Low Variable | High Variable | Fixed Cost |
|---|--------------|---------------|------------|
| Stock refinish - part shotgun/lever gun | \$150 | \$400 | |
| Stock refinish - rifle | \$150 | \$350 | |
| Pillar bed rifle (does not include pillars) | \$100 | \$150 | |
| Glass bed rifle | \$200 | \$300 | |
| Install grind to fit recoil pad (does not include pad) | \$80 | \$120 | |
| Install adjustable buttplate (does not include hardware) | \$120 | \$160 | |
| Install sling swivel, per swivel (does not include swivels) | \$20 | \$60 | |
| Inlet semi-inlet stock | \$200 | \$350 | |
| Transfer fee if no other services | | | \$100 |
| Transfer fee if other services being provided | | | \$30 |
| Multiple handgun surcharge (per gun) | | | \$30 |
| Test fire ammo, parts, services | | | 30% markup |

Fixed - The cost for the service is flat.

Low Variable - The work coming in is in generally good condition or is very simple.

Example: A single shot rifle needs to get pillar and glass bedding done.

Example2: A stock with some minor scratches from years of hunting trips comes in for a refinish.

High Variable - The work coming in is in poor condition, complex, or rare

Example: A hunting rifle which was left out in the elements for months with no protection comes in for cleaning Example2: A stock which was used as a hammer for a home construction project comes in for a refinish Example3: Your great great great grandfathers WWI rifle he brought back from the war needs to be cleaned and refinished before it goes onto a wall